

## ERRATA SHEET No. 1 (for Electronics Technicians)

Engineering Division

W/OPS12: WDW

Additional sites authorized to perform Modification Note 64

**GENERAL:**

This errata sheet includes an additional fifteen (15) sites authorized to install the S100-FMK088, which will provide uninterruptible power supply (UPS) power to the acquisition control unit cabinet. The sites listed in this errata have been authorized by the National Weather Service Change Form S01101 and S01136.

**PROCEDURE:**

Delete BJJ (Wooster, OH) from the table in appendix A, page A-1. The UPS unit previously designated for BJJ will be deployed to MNN instead.

Append the following table to Modification Note 64, page A-3.

Additional Sites to Install a UPS into the ACU			
Site ID	City, State	Region	Authorization #
CEC	Crescent City, CA	Western	S01136
DLN	Dillon, MT	Western	S01136
DUG	Douglas Bisbee, AZ	Western	S01136
FDY	Findlay, OH	Central	S01101
GKJ	Meadville, PA	Eastern	S01101
MLF	Milford, UT	Western	S01136
MNN	Marion, OH	Central	S01101
MYL	McCall, ID	Western	S01136
OLS	Nogales, AZ	Western	S01136
OVE	Oroville, CA	Western	S01136
SDB	Sandberg, CA	Western	S01136
SIY	Montague, CA	Western	S01136
SJN	St. Johns, AZ	Western	S01136
TDZ	Toledo, OH	Central	S01101
UKI	Ukiah, CA	Western	S01136

**EFFECT ON OTHER INSTRUCTIONS:**

None

John McNulty  
Chief, Maintenance, Logistics and Acquisition Division

W/OPS12:W.Whisel:713-1833x156  
File:K:\OSO32\OSO321\ASOS Temps\Errata 1-Mod64.wpd  
spellcheck:10/13/00:src